

FIG 1




FIG 2




FIG 3

ER 27258135905

A hand-drawn perspective view of a rectangular box or container assembly. The drawing includes several labels with leader lines pointing to specific parts:

- 76**: Points to the top-left corner edge.
- 80**: Points to the top surface.
- 78**: Points to the front face.
- 64**: Points to the top-right corner edge.
- 72**: Points to the top edge.
- 30**: Points to a small protrusion or feature on the top surface.
- 63**: Points to a horizontal line or seam on the front face.
- 78**: Points to the right side face.
- 62**: Points to a vertical line or seam on the front face.
- 70**: Points to the bottom edge of the front face.
- 60**: Points to the bottom edge of the right side face.
- 74a**: Points to the top edge of the right side face.
- 74b**: Points to the back face.
- 74c**: Points to the bottom edge of the back face.
- 68**: Points to the bottom edge of the front face.
- 54**: Points to a small feature at the bottom-left corner.
- 66**: Points to a horizontal line or seam near the bottom.
- 78**: Points to the bottom edge of the left side face.
- 80**: Points to the bottom surface.

The drawing uses solid lines for visible edges and dashed lines for hidden internal edges to show the three-dimensional structure.

74a

ER 272581 35905